

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

Approved For Release 2007/01/17 : CIA RDP81B00879R000500080222-7

No. 11921

DATE REC'D. 4-15-57

P.O. NO. 1552

VENDOR PACKING SLIP NO. 45553

O ACCT. OR

R W.O. NO.

S.O. NO.

Industrial Office Supply

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY	REMARKS
QUANTITY RECEIVED									ACCEPTED	REJECTED
3	322	000000	EL	X	43				3	New Stock
DRAWING NO. AND DESCRIPTION										
3 735451-040 Aerial Photo Slide Rule Type Picket-Excel's #700										
STAT										
INSPECTED BY <i>JHC</i> DATE 4-15-57										
REJECTS RETURNED ON SHIP. MEMO NO. _____										

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11932

DATE REC'D. 4-23-57

P.O. NO. 1552

VENDOR PACKING SLIP NO. 45554

O ACCT. OR

R W.O. NO.

S.O. NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY	REMARKS
QUANTITY RECEIVED									ACCEPTED	REJECTED
38	322	000000	022		43				58	2-A4195
38 735453-026 Connector, 15A, 125V, with cord #312										
50 Insulator Connectors 54-104 1/2-10										
Note: Item 1 overshipment of 2 Item 2 not requisitioned overshipment of 50										
STAT										
INSPECTED BY <i>JHC</i> DATE 4-23-57										
REJECTS RETURNED ON SHIP. MEMO NO. _____										

Approved For Release 2007/01/17 : CIA RDP81B00879R000500080222-7

REJECTS RETURNED

ON SHIP. MEMO NO. _____